

**United States Environmental Protection Agency
Region V
POLLUTION REPORT**

EPA Region 5 Records Ctr.



282129

Date: Friday, June 29, 2007**From:** Brian Kelly, OSC

To: Linda M. Nachowicz, U.S. EPA
Mark Durno, EPA
Beverly Kush, U.S. EPA
Tracy Johnson, U.S. EPA
John Maritote, U.S. EPA
Brian Schlieger, U.S. EPA
Michael Chezik, U.S. DOI
Jane Mackey, Congressman Conyers
Jeffrey Bonkoski, Trenton FD
B Boyle, MDCH
Paul Owens, MDEQ
Tom Sampson, MDEQ
Edward Novak, MDEQ
Mark Hammond, Wayne County

Jason El-Zein, U.S. EPA
David Chung, U.S. EPA - HQ
Barbara Carr, U.S. EPA
Stuart Hill, U.S. EPA
A Marouf, U.S. EPA
Mick Hans, U.S. EPA
Dan Sheill, U.S. FWS
Duty Officer, NRC
Dave Michalak, Trenton FD
Joe Walczak, MDEQ
Dan Yordanich, MDEQ
Richard Conforti, MDEQ
Tracy Kecskemeti, MDEQ
Susan Thompson, Wayne County

Subject: Initiation of Action
DSC Trenton
Trenton, MI
Latitude: 42.1636
Longitude: -83.1703

POLREP No.:	1	Site #:	
Reporting Period:		D.O. #:	
Start Date:	6/14/2007	Response Authority:	CERCLA/OPA
Mob Date:	6/14/2007	Response Type:	Emergency
Completion Date:		NPL Status:	Non NPL
CERCLIS ID #:		Incident Category:	Removal Assessment
RCRIS ID #:		Contract #	
FPN#		Reimbursable Account #	

Site Description

The DSC-Trenton Site (aka Detroit Steel Co formerly McLouth Steel) is a former steel production facility located at 1491 West Jefferson Avenue, Trenton, Michigan.

The facility in Trenton and a sister facility in Gibraltar, Michigan are the subject of a 1999 Michigan Department of Environmental Quality (DEQ) Comprehensive Corrective Action and Remedial Consent Order (Order). The Order among other things requires the Trenton facility to collect and remove oil from a basement.

On June 14, 2007, an open pond use by DSC to collect oil caught fire. Trenton Fire Department and the Downriver Emergency Response Team (DERT) responded.

According to the fire department's after action report, the fire cause heavy black smoke that moved toward a graduation ceremony being held at the local high school. DERT air monitoring showed

the area to be safe.

Because the 200-acre Trenton facility has no water supply, fire fighting efforts were delayed while a crash truck from the airport was requested. Application of AFFF foam and 3000 gallons of water extinguished the fire.

During review of the scene, first responders identified hundreds of 5-gallon containers of water-reactive wastes and numerous other 55-gallon drums stored near the location of the fire. DERT requested U.S. EPA assistance. OSC Brian Kelly responded. Due to darkness, a decision was made to further investigate the facility the following day.

Current Activities

On June 15, OSC Kelly, Trenton Fire Captain Jeff Bonkoski and Fire Marshall Dave Michalak conducted a further investigation of the site. During the investigation hundreds of drums, totes, lab chemicals, and other waste containers were found throughout the site. Many of these containers were leaking, unsecured, and accessible to trespassers and the elements. Evidence of trespassing, graffiti, and fence-line breaches was documented (see website photos).

On June 27, OSC Kelly, Fire Marshall Michalak, City of Trenton official Virgil Maiani, U.S. Fish and Wildlife Agent Dan Sheill, and DEQ officials Richard Conforti, Dan Yordanich, Paul Ownes, Tom Sampson, Edward Novak, and Tracy Kecskemeti inspected the site.

Noted during the inspection were the same items identified on June 15, with the addition of dead birds in violation of the Migratory Bird Act and documentation of more than 1,000 unsecured (some leaking into the secondary containment) PCB capacitors.

Planned Removal Actions

Michigan DEQ is preparing to request U.S. EPA assistance with removal of containerized wastes. Following the June 27 inspection, OSC Kelly instructed DSC to:

- 1) collect, secure, stage, sample, and label containerized wastes,
- 2) improve site security and provide a site security plan,
- 3) address health and safety issues such as open pits,
- 4) submit a schedule to accomplish these tasks.

Under the Order, Michigan DEQ will continue to work with DSC to address oil removal. If DSC does not comply with the Order, DEQ may request U.S. EPA assistance.

Next Steps

Oversee efforts of DSC, provide assistance to Michigan DEQ and Trenton Fire Department.

Estimated Costs *

	Budgeted	Total To Date	Remaining	% Remaining
Extramural Costs				
Intramural Costs				
USEPA	\$0.00	\$1,500.00	(\$1,500.00)	0.00%
Total Site Costs				
	\$0.00	\$1,500.00	(\$1,500.00)	0.00%

* The above accounting of expenditures is an estimate based on figures known to the OSC at the

time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

epaosc.net/dsctrenton